



FIXIT
CLINIC

Do-It-Together Troubleshooting & Repair www.fixitclinic.org

NEAL DENTON

SANTA FE COUNTY SUSTAINABILITY SPECIALIST



WARNING:

TO PREVENT ELECTRIC SHOCK
DO NOT REMOVE BACK COVER
NO SERVICEABLE PARTS INSIDE

Frequency Range:

FM 88 - 108 MHz

AM 530-1610 KHz

Power Consumption : 9W

Power Source : AC 220V

CAUTION

RISK OF ELECTRIC SHOCK
DO NOT OPEN

CAUTION:
TO REDUCE THE RISK OF ELECTRIC SHOCK
DO NOT REMOVE COVER
NO SERVICEABLE PARTS INSIDE



Pentalobe Screws




MY ENGINE'S MAKING A WEIRD
NOISE. CAN YOU TAKE A LOOK?

SURE, JUST POP THE HOOD.

OH, THE HOOD LATCH
IS ALSO BROKEN.

OK, JUST PULL UP TO THAT
BIG PIT AND PUSH THE CAR IN.
WE'LL GO GET A NEW ONE.







































































FIXIT
CLINIC

Together Troubleshooting & Repair www.fixitclinic.org