

The City Of Albuquerque IPF- OSHA Experience The Reality Show

Genaro Tafoya
Solid Waste
Management Dept.


Background

- State OSHA inspection September 2008
- Whistle-blower
- Found no violation for alleged complaint
- Full-blown OSHA inspection anyway
- Approx. 30 serious and other violations documented, half abated before formal letter sent
- SWMD shut down IPF for one week

Violations

- Lock-out / tag-out
- Guards
- Walking surfaces
- Fire extinguishers
- PPEs
- Housekeeping
- Documentation
- Haz Comm / Evacuation

After—Evacuation Routes



Before--Spool



After--Spool



Before—Chain Guard



After—Chain Guard



Before--Guard



After--Guard



Before—Ladder Cage



After—Ladder Cage



Before--Guard



After--Guard



Before—Fire Extinguisher



After—Fire Extinguisher



Before—Stair Tread



After—Stair Tread



Before—Fire Extinguisher



After—Fire Extinguisher



After—Chain Guard



After—Chain Guard



After—Chain Guard



After--PPE



Before--Housekeeping



Before—Fire Extinguisher



Before—Fire Ext / Housekeeping



Before—Electrical Panel



Before--Housekeeping / Electrical



Before—Housekeeping/Flammable



Before--Guard



Before—Chain Guard



After—Chain Guard

